


TABLE INSTRUCTIONS



B #10 x 3-1/2" Flathead Screw

HARDWARE &

TOOLS REQUIRED FOR ASSEMBLY 2/4

REQUIRED TOOLS (NOT INCLUDED) - POWER DRILL - #2 SQUARE DRIVE

NOTE: IT IS IMPORTANT TO KEEP ALL SCREWS LOOSE DURING ASSEMBLY UNTIL ENTIRE TABLE IS ASSEMBLED

